



Bergebyvägen 49B SE-685 30 Torsby SWEDEN

Ph. Office: +46 (0)560-126 01

www.wermlandsflyg.se

SE-HIN Summary View

Registration SE-HIN Date **aug 8, 2017**
 Make Sikorsky TAF 8282.6
 Model 269C Serial No. 1280749

Actions

Bat - Battery replacement
 Che - Check replacement
 Hyd - Hydrostatic Test
 Ins - Inspection
 Maj - Major/minor overhaul
 Rep - Replacement
 Tes - Test

Cycles values							
Cycle Name	Value	Cycle Name	Value	Cycle Name	Value	Cycle Name	Value
Flight Segment	0.0	Landings	0.0				

Components									
Component/Action	Part No.	Serial No.	Limit	Perf.	Time at Inst.	Due	TTSC	TTSN	Rem.
Airspeed indicator / Tes 3100	8000	133080	24.0M	8281.1H jan 30, 17		jan 31, 19	1.5H 6.3M		17.8M
Altimeter / Tes 3100	5934P-1	6E416	24.0M	8281.1H jan 30, 17		jan 31, 19	1.5H 6.3M		17.8M
Battery / Che 2400	G-242	G02883713	800.0H 12.0M	8269.6H sep 18, 16		9069.6H sep 18, 17	13.0H 10.7M		787.0H 1.3M
Belt drive system / 6300									
-- Idler pulley bearings / Rep 6300	269A5050-74	NSN	3000.0H	7241.8H dec 22, 06		10241.8H	1040.8H 127.5M		1959.2H
-- Lower pulley coupling shaft / Lif 6300 **Linked AD: ASB B-307A	269A5559-3	S-1326	6000.0H	8269.6H sep 18, 16	2987.8H	11281.8H	3000.8H 10.7M	3000.8H	2999.2H
-- Pulley bearings (Lower) / Rep 6300	269A5050-80	NSN	1800.0H	8104.4H dec 4, 12		9904.4H	178.2H 56.1M		1621.8H
-- Pulley bearings (Upper) / Rep 6300	269A5050-56	NSN	600.0H	8104.4H dec 4, 12		8704.4H	178.2H 56.1M		421.8H
ELT / Tes 2500	E-01	29986	12.0M	8269.6H sep 18, 16		sep 18, 17	13.0H 10.7M		1.3M
-- ELT battery / Bat 2500			24.0M	8281.1H jan 30, 17		jan 30, 19	1.5H 6.3M		17.7M
Engine / Ove		RL-24591-51A	1500.0H 144.0M	7241.8H dec 22, 06		8741.8H dec 22, 18	1040.8H 127.5M	3271.6H	459.2H 16.5M
-- Alternator / Ove 2400	LW-14357	1090871	1500.0H	7922.0H aug 2, 11	2.5H	9419.5H	363.1H 72.2M		1136.9H
-- Alternator brush		NSN	500.0H	7922.0H	2.5H	8419.5H	363.1H		136.9H

Components									
Component/Action	Part No.	Serial No.	Limit	Perf.	Time at Inst.	Due	TTSC	TTSN	Rem.
inspection / Che 2400				aug 2, 11			72.2M		
-- Fuel injector / Ove 7300	2524347-10	30183	1500.0H	7287.2H dec 10, 07		8787.2H	995.4H 115.9M		504.6H
-- Fuel pump / Ove 7300	LW-15479		1500.0H	7241.8H dec 22, 06	54.0H	8687.8H	1094.8H 127.5M		405.2H
-- Induction air filter / Lif 7200	BA-2	NSN	200.0H	8210.3H sep 14, 14		8410.3H	72.3H 34.8M		127.7H
-- Magneto (L/H) / Ove 7400	4345	06020480	1500.0H	7241.8H dec 22, 06		8741.8H	1040.8H 127.5M		459.2H
-- Magneto (R/H) / Ove 7400	4345	06020479	1500.0H	7241.8H dec 22, 06		8741.8H	1040.8H 127.5M		459.2H
-- Starter / Ove 8000	ERB-8011	1061644	1500.0H	7587.2H sep 9, 09		9087.2H	695.4H 95.0M		804.6H
Fire extinguisher / Hyd 2600	A344T	B74104533	144.0M	sep 18, 16		sep 18, 28	10.7M		133.3M
-- Fire extinguisher / Ins 2600			12.0M	8269.6H sep 18, 16		sep 18, 17	13.0H 10.7M		1.3M
First aid kit / Che 2500			12.0M	8269.6H sep 18, 16		sep 18, 17	13.0H 10.7M		1.3M
Lateral pitch mixer bellcrank / Lif 6700	269A7508	1228	32700.0H	0.0H dec 1, 78		32700.0H	8282.6H 464.2M		24417.4H
Main rotor assembly / 6200									
-- Elastomeric damper assy (Blue) / Lif 6600	269A1290-1	1887	6000.0H	7616.3H dec 18, 09	1267.0H	12349.3H	1933.3H 91.7M		4066.7H
-- Elastomeric damper assy (Red) / Lif 6600	269A1290-1	2554	6000.0H	7616.3H dec 18, 09	1551.8H	12064.5H	2218.1H 91.7M		3781.9H
-- Elastomeric damper assy (Yellow) / Lif 6600	269A1290-3	4986	6000.0H	7616.3H dec 18, 09	182.0H	13434.3H	848.3H 91.7M		5151.7H
-- Main rotor blade assy (Blue) / Lif 6600	269A1185-1	002222-6140	5500.0H	7241.8H dec 19, 06	3804.8H	8937.0H	4845.6H 127.6M		654.4H
-- Main rotor blade assy (Red) / Lif 6600	269A1185-1	3798	5500.0H	7241.8H dec 19, 06	3794.3H	8947.5H	4835.1H 127.6M		664.9H
-- Main rotor blade assy (Yellow) / Lif 6600	269A1185-1	002222-6142	5500.0H	7241.8H dec 19, 06	3804.8H	8937.0H	4845.6H 127.6M		654.4H
-- Main rotor hub	269A1232	NSN	1900.0H	6805.0H		8705.0H	1477.6H		422.4H

Components									
Component/Action	Part No.	Serial No.	Limit	Perf.	Time at Inst.	Due	TTSC	TTSN	Rem.
bolts (All (6 ea)) / Lif 6200				feb 20, 99			221.6M		
-- Main rotor pitch bearing shaft (Blue) / Lif 6200	269A1240-7	S5995	3600.0H	7185.5H maj 28, 03		10785.5H	1097.1H 170.3M		2502.9H
-- Main rotor pitch bearing shaft (Red) / Lif 6200	269A1240-7	S6048	3600.0H	7185.5H maj 28, 03		10785.5H	1097.1H 170.3M		2502.9H
-- Main rotor pitch bearing shaft (Yellow) / Lif 6200	269A1240-7	S6079	3600.0H	7185.5H maj 28, 03		10785.5H	1097.1H 170.3M		2502.9H
Main rotor mast / Lif 6300	269A2010-5	0817	13590.0H	0.0H dec 1, 78		13590.0H	8282.6H 464.2M		5307.4H
-- Main rotor drive shaft (oil filled) / Lif 6300 **Linked AD: AD 95-21-02	269A5305-111M	SZ0374M	1900.0H	6805.0H feb 20, 99		8705.0H	1477.6H 221.6M		422.4H
-- Main rotor thrust bearing / Lif 6600	269A5050-63	4582	3000.0H	7385.4H aug 13, 08		10385.4H	897.2H 107.8M		2102.8H
Main transmission / Maj 6300	269A5175-7	961032W	3000.0H	7057.0H maj 25, 01		10057.0H	1225.6H 194.4M		1774.4H
-- Main gearbox pinion / Lif 6300	269A5103-9	314042	6000.0H	7057.0H maj 25, 01	2271.7H	10785.3H	3497.3H 194.4M		2502.7H
-- Main rotor drive ring gear carrier assembly / Lif 6300	269A5194	1160146	6000.0H	7057.0H maj 25, 01	2262.2H	10794.8H	3487.8H 194.4M		2512.2H
PLB / Che 2500		379870	12.0M	jun 21, 17		jun 21, 18	1.6M		10.4M
-- PLB / Bat 2500		15400512	*	jun 21, 17 *	*	jun 30, 23 *	1.6M*	*	70.7M*
Tail rotor /									
-- Tail rotor blade assembly / Lif 6400	269A6035-23	0861	9000.0H	0.0H dec 1, 78		9000.0H	8282.6H 464.2M		717.4H
-- Tail rotor blade assembly / Lif 6400	269A6035-23	0862	9000.0H	0.0H dec 1, 78		9000.0H	8282.6H 464.2M		717.4H
-- Tail rotor drive shaft assembly / Lif 6400	269A6040-7	S1446	6000.0H	6058.0H jan 24, 93		12058.0H	2224.6H 294.5M		3775.4H
-- Tail rotor retention straps / Lif 6400 **Linked AD: AD 88-12-02	369A1706-507	S0553	5100.0H	5483.0H mar 13, 89	477.0H	10106.0H	3276.6H 340.8M		1823.4H
Tail rotor transmission / Ove 6500	269A6027-56	B642	3000.0H	6157.1H okt 14, 93	39.7H	9117.4H	2165.2H 285.8M		834.8H

Components									
Component/Action	Part No.	Serial No.	Limit	Perf.	Time at Inst.	Due	TTSC	TTSN	Rem.
-- Tail rotor gear shaft input assembly / Lif 6600	369A5425-5	12683644	8600.0H	6157.1H okt 14, 93	3909.7H	10847.4H	6035.2H 285.8M		2564.8H
Tailboom assembly / Lif 6600	269A2320-11W	S1377	2100.0H	6310.3H jul 7, 94		8410.3H	1972.3H 277.0M		127.7H
-- Horizontal stabilizer assembly / Lif 6600	269A2516-21	S1084	4200.0H	7496.2H feb 5, 09		11696.2H	786.4H 102.1M		3413.6H
-- Tailboom attaching strut assembly / Lif 6600	269A2015-11	1920	10700.0H	0.0H dec 1, 78		10700.0H	8282.6H 464.2M		2417.4H
-- Tailboom attaching strut assembly / Lif 6600	269A2015-11	1921	10700.0H	0.0H dec 1, 78		10700.0H	8282.6H 464.2M		2417.4H
-- Vertical stabilizer assembly / Lif 6600	269A2419-3	0884	20540.0H	0.0H dec 1, 78		20540.0H	8282.6H 464.2M		12257.4H

" * " indicates that a Manual Next Due is set.

Recurring AD's								
AD No.	Description	Type	Limit	Perf.	Due	TTSC	TTSN	Rem.
AD 2005-0023 R3 Engine 7200	Exhaust valve inspection. Engine RL-24591-51A	Recur	300.0H	8021.7H mar 23, 12	8321.7H	260.9H 64.5M		39.1H
AD 2015-19-07 Engine 7300	External fuel injector lines. Engine RL-24591-51A	Recur	50.0H	8269.6H sep 18, 16	8319.6H	13.0H 10.7M		37.0H
AD 2017-14-06 Airframe 6300	Lower coupling drive shaft inspection. Lower pulley coupling shaft 3995	Recur	150.0H	8269.6H sep 18, 16	8419.6H	13.0H 10.7M		137.0H
AD 76-07-12 Engine 7400	Ignitions switch check.	Recur	12.0M	8269.6H sep 18, 16	sep 18, 17	13.0H 10.7M		1.3M
AD 79-23-03 R1 Airframe 6400	Tail rotor blade spar inspection.	Recur	600.0H 12.0M	8269.6H sep 18, 16	8869.6H sep 18, 17	13.0H 10.7M		587.0H 1.3M
AD US-2015-23-01 Airframe 6500	Tail rotor drive.	Recur	100.0H	8269.6H sep 18, 16	8369.6H	13.0H 10.7M		87.0H
LSB 301B Engine 7200	Valve inspection. Engine RL-24591-51A	Recur	300.0H	8021.7H mar 23, 12	8321.7H	260.9H 64.5M		39.1H
LSB 480E Engine 7900	Oil and filter change. Engine RL-24591-51A	Recur	50.0H	8281.1H jan 30, 17	8331.1H	1.5H 6.3M		48.5H

" * " indicates that a Manual Next Due is set.

Inspections					
Inspection	Limit	Perf.	Due	TTSC	Rem.
100 hrs inspection	100.0H	8210.3H sep 11, 14	8310.3H	72.3H 34.9M	27.7H
12 month inspection	12.0M	8269.6H sep 18, 16	sep 18, 17	13.0H 10.7M	1.3M
1200 hrs inspection	1200.0H	8104.4H dec 4, 12	9304.4H	178.2H 56.1M	1021.8H
150 hrs inspection	150.0H	8269.6H sep 18, 16	8419.6H	13.0H 10.7M	137.0H
200 hrs inspection	200.0H	8104.4H dec 4, 12	8304.4H	178.2H 56.1M	21.8H
25 hrs inspection	25.0H	8269.6H sep 18, 16	8294.6H	13.0H 10.7M	12.0H
300 hrs inspection	300.0H	8021.7H mar 23, 12	8321.7H	260.9H 64.5M	39.1H
400 hrs inspection	400.0H	8104.4H dec 4, 12	8504.4H	178.2H 56.1M	221.8H
50 hrs inspection	50.0H	8264.6H feb 11, 15	8314.6H	18.0H 29.9M	32.0H
600 hrs inspection	600.0H	8104.4H dec 4, 12	8704.4H	178.2H 56.1M	421.8H
Compass swing	24.0M	8269.6H sep 18, 16	sep 18, 18	13.0H 10.7M	13.3M
Drive system bearings clean/insp/repack	24.0M	8281.1H jan 30, 17	jan 31, 19	1.5H 6.3M	17.8M
H-frame bearings lubrication, all (upper, lower and idler pulley)	300.0H 12.0M	8269.6H sep 18, 16	8569.6H sep 18, 17	13.0H 10.7M	287.0H 1.3M
Main rotor drive shaft oil level check (269A5305-111M)	12.0M	8269.6H sep 18, 16	sep 18, 17	13.0H 10.7M	1.3M
Main rotor swashplate bearing insp/repack (269A1331-5)	1200.0H 12.0M	8269.6H sep 18, 16	9469.6H sep 18, 17	13.0H 10.7M	1187.0H 1.3M
Main rotor thrust bearing lube (269A5050-63)	600.0H 12.0M	8269.6H sep 18, 16	8869.6H sep 18, 17	13.0H 10.7M	587.0H 1.3M
Tail rotor blade inspection (269A6035-23)	600.0H 12.0M	8269.6H sep 18, 16	8869.6H sep 18, 17	13.0H 10.7M	587.0H 1.3M
Tail rotor swashplate bearing insp/repack (269A6050-5)	1200.0H 12.0M	8269.6H sep 18, 16	9469.6H sep 18, 17	13.0H 10.7M	1187.0H 1.3M

" * " indicates that a Manual Next Due is set.

Elastomeric damper assy (Blue) - Assembly - PN: 269A1290-1 SN: 1887									
Component/Action	Part No.	Serial No.	Limit	Perf.	Time at Inst.	Due	TTSC	TTSN	Rem.
Elastomeric damper assy (Blue) / Lif 6600	269A1290-1	1887	6000.0H	7616.3H dec 18, 09	1267.0H	12349.3H	1933.3H 91.7M		4066.7H
-- Elastomeric damper assy inspection (After 4200 hrs TTIS) (Blue) / Ins 6600	269A1290-1	1887	300.0H*	7616.3H* dec 18, 09	1267.0H*	10549.3H*	1933.3H* 91.7M	*	2266.7H*
-- Elastomeric damper assy inspection (Up to 4200 hrs TTIS) (Blue) / Ins 6600	269A1290-1	1887	600.0H	8104.4H dec 4, 12		8704.4H	178.2H 56.1M		421.8H

" * " indicates that a Manual Next Due is set.

Elastomeric damper assy (Red) - Assembly - PN: 269A1290-1 SN: 2554									
Component/Action	Part No.	Serial No.	Limit	Perf.	Time at Inst.	Due	TTSC	TTSN	Rem.
Elastomeric damper assy (Red) / Lif 6600	269A1290-1	2554	6000.0H	7616.3H dec 18, 09	1551.8H	12064.5H	2218.1H 91.7M		3781.9H
-- Elastomeric damper assy inspection (After 4200 hrs TTIS) (Red) / Ins 6600	269A1290-1	2554	300.0H*	7616.3H* dec 18, 09	1551.8H*	10264.5H*	2218.1H* 91.7M	*	1981.9H*
-- Elastomeric damper assy inspection (Up to 4200 hrs TTIS) (Red) / Ins 6600	269A1290-1	2554	600.0H	8104.4H dec 4, 12		8704.4H	178.2H 56.1M		421.8H

" * " indicates that a Manual Next Due is set.

Elastomeric damper assy (Yellow) - Assembly - PN: 269A1290-3 SN: 4986									
Component/Action	Part No.	Serial No.	Limit	Perf.	Time at Inst.	Due	TTSC	TTSN	Rem.
Elastomeric damper assy (Yellow) / Lif 6600	269A1290-3	4986	6000.0H	7616.3H dec 18, 09	182.0H	13434.3H	848.3H 91.7M		5151.7H
-- Elastomeric damper assy inspection (After 4200 hrs TTIS) (Yellow) / Ins 6600	269A1290-3	4986	300.0H*	7616.3H* dec 18, 09	182.0H*	11634.3H*	848.3H* 91.7M	*	3351.7H*
-- Elastomeric damper assy inspection (Up to 4200 hrs TTIS) (Yellow) / Ins 6600	269A1290-3	4986	600.0H	8104.4H dec 4, 12		8704.4H	178.2H 56.1M		421.8H

" * " indicates that a Manual Next Due is set.

Magneto (L/H) - Assembly - PN: 4345 SN: 06020480									
Component/Action	Part No.	Serial No.	Limit	Perf.	Time at Inst.	Due	TTSC	TTSN	Rem.
Magneto (L/H) / Ove 7400	4345	06020480	1500.0H	7241.8H dec 22, 06		8741.8H	1040.8H 127.5M		459.2H
-- Magneto 500 hrs internal inspection (L/H) / 7400			500.0H	8227.2H jan 11, 15		8727.2H	55.4H 30.9M		444.6H

" * " indicates that a Manual Next Due is set.

Magneto (R/H) - Assembly - PN: 4345 SN: 06020479									
Component/Action	Part No.	Serial No.	Limit	Perf.	Time at Inst.	Due	TTSC	TTSN	Rem.
Magneto (R/H) / Ove 7400	4345	06020479	1500.0H	7241.8H dec 22, 06		8741.8H	1040.8H 127.5M		459.2H
-- Magneto 500 hrs internal inspection (R/H) / Ins 7400			500.0H	8227.2H jan 11, 15		8727.2H	55.4H 30.9M		444.6H

" * " indicates that a Manual Next Due is set.